

## Luna Triple 32x140 - B quality



Example of the surface of Luna Triple 32x140 B quality.

### Main defects in Luna Triple 32x140 B quality

Knot defects like splits and holes are the main reason that causes B quality of Luna Triple 32x140. Other defects are mostly mechanical due to planing errors and/or end splits.

Depending on the quality requirements of the end use application, expected utility estimate is about 60%. Defects that are mentioned above, effects mostly to the visual outlook of the product. Durability and technical performance are still on a very high level despite the visual defects.

Other quality descriptions can be found from the Lunawood's general quality description for B quality.