

LUNAWOOD PLANED WW B-QUALITY



Main defects in spruce B quality

Knot defects like splits and broken knots are the main reason that causes B quality of spruce. Other defects are mostly mechanical due to planing errors and/or end and surface splits. Depending on the quality requirements of the end use application, expected utility estimate is about 70%. Defects that are mentioned above, effects mostly to the visual outlook of the product. Durability and technical performance are still on a very high level despite the visual defects. Other quality descriptions can be found from the Lunawood's general quality description for B-quality. Durability and technical performance are still on a very high level despite the visual defects. Other quality descriptions can be found from the Lunawood's general quality description for B-quality.